

This modification replaces the standard RS422 line driver IC with the SN74265 line driver.

Connections can be found on the model specific datasheet under the heading "Line Driver Outputs".

This option is not recommended for new designs.

Rev	Description	Date	This information is approved only if it is stamped "APPROVED", signed, and dated.	Tolerances	MI81: 74265 line driver output circuit		
			This document is provided for a specific purpose and the disclosed information remains our property. It may not be disclosed, copied, or reproduced, except for the specific purpose, without Photocraft's prior approval. This notice must appear on any copy or reproduction of this document. © 2004, Photocraft Inc.	.XXXX ± .0005 .XXX ± .005 .XX ± .01 .X ± .015 Fractions ± 1/32 Angles ± 15 min Runout ± .003 <small>unless otherwise specified</small>	By: TRD	Mat'l: n/a	
					Orig. Date: 3/10/05	Finish: n/a	Scale: n/a
					Photocraft Inc 602 E. North Street, Elburn IL 60119, USA www.photocraftencoders.com		8A181